





TDK Corporation

## HHM1715E1


Inombolo Yengxenywe:  
 Umkhiqizi / Umkhiqizo:  
 Incazelo yomkhiqizo  
 Amadokhumenti:  
 Isimo se-RoHS  
 Umkhumbi ovela  
 Ukuthunyelwa Kwendlela

HHM1715E1  
 TDK Corporation  
 BALUN 3.3GHZ-3.9GHZ 50/100 0603  
 [HHM1715E1.pdf](#)  
 Qondisa mahhala / i-RoHS Compliant  
 i-Hong Kong  
 DHL/Fedex/TNT/UPS/EMS

**ISICELO SOKUCAPHUNA**

Isithombe singabekwa. Bheka imininingwane yemininingwane yomkhiqizo.













### Imininingwane ye-HHM1715E1

INOMBOLO YENGXENYE	HHM1715E1
UMKHIQIZI	TDK Corporation
INCAZELO	BALUN 3.3GHZ-3.9GHZ 50/100 0603
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Qondisa mahhala / i-RoHS Compliant
ISHIDI LE-DATA	 <a href="#">HHM1715E1.pdf</a>
UCHUNGECHUNGE	HHM
BUYISELA UKULAHLEKELWA (MIN)	10dB
UKUHLUKAHLUKA KWESIGABA	180° ±15°
UKUPAKISHA	Cut Tape (CT)
IPHAKHEJI / ICALA	0603 (1608 Metric)
AMANYE AMAGAMA	445-3995-1
UHLOBO LOKUFAKA	Surface Mount
IZINGA LOKUZWELA UKUTHUTHA (MSL)	1 (Unlimited)
ISIKHATHI SESIKHATHI ESIYISIBONELO SOKUKHIQIZA	12 Weeks
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Lead free / RoHS Compliant
UKUNGENA OKUFAKIWE (I-MAX)	1.0dB
UKUPHELELWA ISIKHATHI - UKUNGALINGANI / UKULINGANISELA	50 / 100 Ohm
UKWABELANA NGAMAVOLUMU	3.3GHz ~ 3.9GHz
INCAZELO EPHELELE	RF Balun 3.3GHz ~ 3.9GHz 50 / 100 Ohm 0603 (1608 Metric)

### Amathegi ahlobene

I-TDK Corporation HHM1715E1	Umsabalalisi we-HHM1715E1	Umhlinzeki we-HHM1715E1
Intengo ye-HHM1715E1	Izithombe ze-HHM1715E1	HHM1715E1 Image
Idatha ye-HHM1715E1 PDF	I-HHM1715E1 Landa iDatasheet	Idatha ye-HHM1715E1
HHM1715E1 stock	Thenga i-HHM1715E1	Thenga i-TDK Corporation HHM1715E1
I-TDK Corporation HHM1715E1	Umphekeli we-TDK Corporation	Umsabalalisi we-TDK Corporation
I-TDK Corporation HHM1715E1		

### Imikhiqizo ehlobene

 <p><b>HHM1727D1</b>                  Abakhiqizi: TDK Corporation                  Incazelo: BALUN 3.3GHZ-3.9GHZ 50/50 0603                  Kukhona kusitoki: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM17165A1</b>                  Abakhiqizi: TDK Corporation                  Incazelo: BALUN 2.4GHZ-2.8GHZ 50/50 0603                  Kukhona kusitoki: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM17166A1</b>                  Abakhiqizi: TDK Corporation                  Incazelo: BALUN 1.9GHZ-2.3GHZ 50/50 0603                  Kukhona kusitoki: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM17153A2</b>                  Abakhiqizi: TDK Corporation                  Incazelo: BALUN 698MHZ-894MHZ 50/50 0603                  Kukhona kusitoki: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM17168B1</b>                  Abakhiqizi: TDK Corporation                  Incazelo: BALUN 3.4GHZ-3.8GHZ 50/50 0603                  Kukhona kusitoki: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM17144A1</b>                  Abakhiqizi: TDK Corporation                  Incazelo: BALUN 791MHZ-894MHZ 50/100 0603                  Kukhona kusitoki: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM17146A1</b>                  Abakhiqizi: TDK Corporation                  Incazelo: BALUN 1.92GHZ-2.17GHZ 50/50 0603                  Kukhona kusitoki: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM17139B1</b>                  Abakhiqizi: TDK Corporation                  Incazelo: BALUN 2.4GHZ-2.5GHZ 50/50 0603                  Kukhona kusitoki: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM17152A1</b>                  Abakhiqizi: TDK Corporation                  Incazelo: BALUN 698MHZ-894MHZ 50/100 0603                  Kukhona kusitoki: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1726N1</b>                  Abakhiqizi: TDK Corporation                  Incazelo: BALUN 824MHZ-915MHZ 50/100 0603                  Kukhona kusitoki: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1726P1</b>                  Abakhiqizi: TDK Corporation                  Incazelo: BALUN 880MHZ-960MHZ 50/100 0603                  Kukhona kusitoki: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM17139B2</b>                  Abakhiqizi: TDK Corporation                  Incazelo: BALUN 2.4GHZ-2.6GHZ 50/50 0603                  Kukhona kusitoki: Out stock</p> <p><b>RFQ</b></p>

