



Pulse Electronics Corporation

TM1062FCA1

| | |
|------------------------|--|
| Inombolo Yengxenywe: | TM1062FCA1 |
| Umkhiqizi / Umkhiqizo: | Pulse Electronics Corporation |
| Incazelo yomkhiqizo | TRANSCEIVER PBC |
| | PDF 1.TM1062FCA1.pdf |
| | PDF 2.TM1062FCA1.pdf |
| Amadokhumenti: | |
| Isimo se-RoHS | Cela ukuqinisekiswa kokusungulwa / i-RoHS engavumelani |
| Umkhumbi ovela | i-Hong Kong |
| Ukuthunyelwa Kwendlela | DHL/Fedex/TNT/UPS/EMS |

ISICELO SOKUCAPHUNA

Isithombe singabekwa. Bheka imininingwane yemininingwane yomkhiqizo.













Imininingwane ye-TM1062FCA1

| | |
|--|--|
| INOMBOLO YENGXENYE | TM1062FCA1 |
| UMKHIQIZI | Pulse Electronics Corporation |
| INCAZELO | TRANSCEIVER PBC |
| ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS | Cela ukuqinisekiswa kokusungulwa / i-RoHS engavumelani |
| ISHIDI LE-DATA | PDF 1.TM1062FCA1.pdf PDF 2.TM1062FCA1.pdf |
| I-VOLTAGE - SUPPLY | 5V |
| THAYIPHA | Transceiver |
| IPHAKHEJI YEDIVAYSI YENSIZA | Module |
| UCHUNGECHUNGE | Copperhead™ |
| I-PROTOCOL | IEEE 1394B |
| IPHAKHEJI / ICALA | 28-SMD Module |
| UKUSHISA OKUSEBENZAYO | -55°C ~ 125°C |
| INANI LABASHAYELI / ABABUKELI | 1/1 |
| UHLORO LOKUFAKA | Surface Mount |
| IZINGA LOKUZWELA UKUTHUTHA (MSL) | 3 (168 Hours) |
| ISIKHATHI SESIKHATHI ESIYISIBONELO SOKUKHIQIZA | 19 Weeks |
| ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS | Request inventory verification / RoHS non-compliant |
| DUPLEX | - |
| INCAZELO EPHELELE | 1/1 Transceiver IEEE 1394B Module |
| ISILINGANISO SEDATHA | 1.062Gbps |

Amathegi ahlobene

| | | |
|--|--|---|
| I-Pulse Electronics Corporation TM1062FCA1 | Umsabalalisi we-TM1062FCA1 | Umhlinzeki we-TM1062FCA1 |
| Intengo ye-TM1062FCA1 | Izithombe ze-TM1062FCA1 | TM1062FCA1 Image |
| Idatha ye-TM1062FCA1 PDF | I-TM1062FCA1 Landa iDatasheet | Idatha ye-TM1062FCA1 |
| TM1062FCA1 stock | Thenga i-TM1062FCA1 | Thenga i-Pulse Electronics Corporation TM1062FCA1 |
| I-Pulse Electronics Corporation TM1062FCA1 | Umphakeli we-Pulse Electronics Corporation | Umsabalalisi we-Pulse Electronics Corporation |
| I-Pulse Electronics Corporation TM1062FCA1 | I-Pulse A Technitrol Company TM1062FCA1 | I-Pulse TM1062FCA1 |

Imikhiqizo ehlobene

| | |
|--|---|
|  <p>TM1062DUXB Abakhiqizi: Pulse Electronics Corporation Incazelo: TRANSCEIVER PBC Kukhona kusitoki: Out stock</p> <p>RFQ</p> |  <p>TM1062HSB1 Abakhiqizi: Pulse Electronics Corporation Incazelo: TRANSCEIVER TM1062HSB1 PBC Kukhona kusitoki: Out stock</p> <p>RFQ</p> |
|  <p>TM1062DVB2 Abakhiqizi: Pulse Electronics Corporation Incazelo: TRANSCEIVER PBC Kukhona kusitoki: Out stock</p> <p>RFQ</p> |  <p>TM1062DUB2 Abakhiqizi: Pulse Electronics Corporation Incazelo: TRANSCEIVER PBC Kukhona kusitoki: Out stock</p> <p>RFQ</p> |
|  <p>TM1062FUB Abakhiqizi: Pulse Electronics Corporation Incazelo: TRANSCEIVER MODULE PBC Kukhona kusitoki: Out stock</p> <p>RFQ</p> |  <p>TM1062DVB Abakhiqizi: Pulse Electronics Corporation Incazelo: TRANSCEIVER MODULE PBC Kukhona kusitoki: Out stock</p> <p>RFQ</p> |
|  <p>TM1062FSB2 Abakhiqizi: Pulse Electronics Corporation Incazelo: TRANSCEIVER MODULE PBC Kukhona kusitoki: Out stock</p> <p>RFQ</p> |  <p>TM1062FCA2 Abakhiqizi: Pulse Electronics Corporation Incazelo: TRANSCEIVER PBC Kukhona kusitoki: Out stock</p> <p>RFQ</p> |
|  <p>TM1062DUA1 Abakhiqizi: Pulse Electronics Corporation Incazelo: TRANSCEIVER PBC Kukhona kusitoki: Out stock</p> <p>RFQ</p> |  <p>TM1062DVA1 Abakhiqizi: Pulse Electronics Corporation Incazelo: MIL-AERO Kukhona kusitoki: Out stock</p> <p>RFQ</p> |
|  <p>TM1062FSB Abakhiqizi: Pulse Electronics Corporation Incazelo: TRANSCEIVER MODULE PBC Kukhona kusitoki: Out stock</p> <p>RFQ</p> |  <p>TM1062FSA Abakhiqizi: Pulse Electronics Corporation Incazelo: TRANSCEIVER PBC Kukhona kusitoki: Out stock</p> <p>RFQ</p> |