



SICK

**DGS35-1L202048**

Inombolo Yengxenywe:	DGS35-1L202048
Umkhiqizi / Umkhiqizo:	SICK
Incazelo yomkhiqizo	ROTARY ENCODR INCREMENT 2048PPR
Amadokhumenti:	
Umkhumbi ovela	i-Hong Kong
Ukuthunyelwa Kwendlela	DHL/Fedex/TNT/UPS/EMS


[ISICELO SOKUCAPHUNA](#)

Isithombe singabekwa. Bheka imininingwane yemininingwane yomkhiqizo.









### Imininingwane ye-DGS35-1L202048

INOMBOLO YENGXENYE	DGS35-1L202048
UMKHIQIZI	SICK
INCAZELO	ROTARY ENCODR INCREMENT 2048PPR
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	
ISHIDI LE-DATA	
I-VOLTAGE - SUPPLY	4.5 V ~ 5.5 V
ISITAYELA SOKUQEDA	Cable
UCHUNGECHUNGE	-
UKUPHILA OKUJIKHEZAYO (AMA-CYCLES MIN)	-
AMAPULISI NGE-REVOLUTION	2048
UHLOBO LOKUPHUMA	-
AMANYE AMAGAMA	1049681
ISIFUNDO	User Selectable
UHLOBO LOKUFAKA	Chassis Mount
ISIKHATHI SESIKHATHI ESIYISIBONELO SOKUKHIQIZA	3 Weeks
UHLOBO LWEKHOWUDI	Incremental
UKUZETHEMBA	No
YAKHELWE KU-SWITCH	No
UHLOBO LWE-ACTUATOR	Hole for Shaft

### Amathegi ahlobene

<a href="#">I-SICK DGS35-1L202048</a>	<a href="#">Umsabalalisi we-DGS35-1L202048</a>	<a href="#">Umhlinzeki we-DGS35-1L202048</a>
<a href="#">Intengo ye-DGS35-1L202048</a>	<a href="#">Izithombe ze-DGS35-1L202048</a>	<a href="#">DGS35-1L202048 Image</a>
<a href="#">Idatha ye-DGS35-1L202048 PDF</a>	<a href="#">I-DGS35-1L202048 Landa iDatasheet</a>	<a href="#">Idatha ye-DGS35-1L202048</a>
<a href="#">DGS35-1L202048 stock</a>	<a href="#">Thenga i-DGS35-1L202048</a>	<a href="#">Thenga i-SICK DGS35-1L202048</a>
<a href="#">I-SICK DGS35-1L202048</a>	<a href="#">Umphekeli we-SICK</a>	<a href="#">Umsabalalisi we-SICK</a>
<a href="#">I-SICK DGS35-1L202048</a>		

### Imikhiqizo ehlobene

 <p><b>DGS35-1LN00120</b> Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENTAL 120PPR Kukhona kusitoki: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1KK02048</b> Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 2048PPR Kukhona kusitoki: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-1KN02048</b> Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 2048PPR Kukhona kusitoki: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1L402500</b> Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 2500PPR Kukhona kusitoki: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-1KK05000</b> Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 5000PPR Kukhona kusitoki: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1KK01024</b> Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 1024PPR Kukhona kusitoki: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-1K405000</b> Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 5000PPR Kukhona kusitoki: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1KK02500</b> Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 2500PPR Kukhona kusitoki: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-1LN01024</b> Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 1024PPR Kukhona kusitoki: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1LM01024</b> Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 1024PPR Kukhona kusitoki: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-1L204096</b> Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 4096PPR Kukhona kusitoki: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1L202500</b> Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 2500PPR Kukhona kusitoki: Out stock</p> <p><a href="#">RFQ</a></p>

I-Copyright © 2020 Distributor Ethembekile Yezingxenywe Ze-elektronikhi - Ocean-Components.com

Imeyili: [I-Info@Ocean-Components.com](mailto:I-Info@Ocean-Components.com)

Ikheli: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

