




AVX Corporation

CP0402A0836ELTR

Inombolo Yengxenywe:
 Umkhiqizi / Umkhiqizo:
 Incazelo yomkhiqizo
 Amadokhumenti:
 Isimo se-RoHS
 Umkhumbi ovela
 Ukuthunyelwa Kwendlela

CP0402A0836ELTR
 AVX Corporation
 RF DIR COUPLER 824-849MHZ 0402
[PDF CP0402A0836ELTR.pdf](#)
 Iqukethe ukuhola / RoHS okungavumelani
 i-Hong Kong
 DHL/Fedex/TNT/UPS/EMS

[ISICELO SOKUCAPHUNA](#)

Isithombe singabekwa. Bheka imininingwane yemininingwane yomkhiqizo.













Imininingwane ye-CP0402A0836ELTR

INOMBOLO YENGXENYE	CP0402A0836ELTR
UMKHIQIZI	AVX Corporation
INCAZELO	RF DIR COUPLER 824-849MHZ 0402
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Iqukethe ukuhola / RoHS okungavumelani
ISHIDI LE-DATA	PDF CP0402A0836ELTR.pdf
IPHAKHEJI YEDIVAYISI YENSIZA	0402
UCHUNGECHUNGE	-
BUYISELA UKULAHLEKELWA	35dB
AMANDLA - MAX	3W
UKUPAKISHA	Tape & Reel (TR)
IPHAKHEJI / ICALA	0402 (1005 Metric)
IZINGA LOKUZWELA UKUTHUTHA (MSL)	1 (Unlimited)
ISIKHATHI SESIKHATHI ESIYISIBONELO SOKUKHIQIZA	10 Weeks
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Contains lead / RoHS non-compliant
UKUHLUKANISWA	-51dB
UKUFELWA KOKUFAKIWE	0.2dB
UKUVAMA	824MHz ~ 849MHz
INCAZELO EPHELELE	RF Directional Coupler AMPS 824MHz ~ 849MHz 27.2dB 3W 0402 (1005 Metric)
FACT FACTOR	27.2dB
UHLOBO LOMBHANGQWANA	Standard
IZICELO	AMPS

Amathegi ahlobene

I-AVX Corporation CP0402A0836ELTR	Umsabalalisi we-CP0402A0836ELTR	Umhlinzeki we-CP0402A0836ELTR
Intengo ye-CP0402A0836ELTR	Izithombe ze-CP0402A0836ELTR	CP0402A0836ELTR Image
Idatha ye-CP0402A0836ELTR PDF	I-CP0402A0836ELTR Landa iDatasheet	Idatha ye-CP0402A0836ELTR
CP0402A0836ELTR stock	Thenga i-CP0402A0836ELTR	Thenga i-AVX Corporation CP0402A0836ELTR
I-AVX Corporation CP0402A0836ELTR	Umphekeli we-AVX Corporation	Umsabalalisi we-AVX Corporation
I-AVX Corporation CP0402A0836ELTR	I-AVX Corporation [MIL] CP0402A0836ELTR	

Imikhiqizo ehlobene

 <p>CP0402A0902ALTR Abakhiqizi: AVX Corporation Incazelo: RF DIR COUPLER 890-915MHZ 0402 Kukhona kusitoki: 256100 pcs</p> <p>RFQ</p>	 <p>CP0402A0836BNTR Abakhiqizi: AVX Corporation Incazelo: RF DIR COUPLER 824-849MHZ 0402 Kukhona kusitoki: 269143 pcs</p> <p>RFQ</p>
 <p>CP0402A0881ANTR Abakhiqizi: AVX Corporation Incazelo: RF DIR COUPLER 890-894MHZ 0402 Kukhona kusitoki: 268043 pcs</p> <p>RFQ</p>	 <p>CP0402A0881ALTR Abakhiqizi: AVX Corporation Incazelo: RF DIR COUPLER 869-894MHZ 0402 Kukhona kusitoki: 311288 pcs</p> <p>RFQ</p>
 <p>CP0402A0836ANTR Abakhiqizi: AVX Corporation Incazelo: RF DIR COUPLER 824-849MHZ 0402 Kukhona kusitoki: 312515 pcs</p> <p>RFQ</p>	 <p>CP0402A0836ENTR Abakhiqizi: AVX Corporation Incazelo: RF DIR COUPLER 869-849MHZ 0402 Kukhona kusitoki: 266104 pcs</p> <p>RFQ</p>
 <p>CP0402A0836CLTR Abakhiqizi: AVX Corporation Incazelo: RF DIR COUPLER 824-849MHZ 0402 Kukhona kusitoki: 280051 pcs</p> <p>RFQ</p>	 <p>CP0402A0836CNTR Abakhiqizi: AVX Corporation Incazelo: RF DIR COUPLER 824-849MHZ 0402 Kukhona kusitoki: 263241 pcs</p> <p>RFQ</p>
 <p>CP0402A0942BLTR Abakhiqizi: AVX Corporation Incazelo: RF DIR COUPLER 925-960MHZ 0402 Kukhona kusitoki: 298807 pcs</p> <p>RFQ</p>	 <p>CP0402A0836ALTR Abakhiqizi: AVX Corporation Incazelo: RF DIR COUPLER 824-849MHZ 0402 Kukhona kusitoki: 307638 pcs</p> <p>RFQ</p>
 <p>CP0402A0836BLTR Abakhiqizi: AVX Corporation Incazelo: RF DIR COUPLER 824-849MHZ 0402 Kukhona kusitoki: 297451 pcs</p> <p>RFQ</p>	 <p>CP0402A0942ALTR Abakhiqizi: AVX Corporation Incazelo: RF DIR COUPLER 925-960MHZ 0402 Kukhona kusitoki: 279032 pcs</p> <p>RFQ</p>