

N/A

CDCV857DGG

Inombolo Yengxenywe:	CDCV857DGG
Umkhiqizi / Umkhiqizo:	N/A
Incazelo yomkhiqizo	IC SSTL-II PLL CLK-DRVR 48TSSOP
Amadokhumenti:	
Isimo se-RoHS	Qondisa mahhala / i-RoHS Compliant
Umkhumbi ovela	i-Hong Kong
Ukuthunyelwa Kwendlela	DHL/Fedex/TNT/UPS/EMS

ISICELO SOKUCAPHUNA

Isithombe singabekwa. Bheka imininingwane yemininingwane yomkhiqizo.

Imininingwane ye-CDCV857DGG

INOMBOLO YENGXENYE	CDCV857DGG
UMKHIQIZI	N/A
INCAZELO	IC SSTL-II PLL CLK-DRVR 48TSSOP
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Qondisa mahhala / i-RoHS Compliant
ISHIDI LE-DATA	
I-VOLTAGE - SUPPLY	2.3 V ~ 2.7 V
THAYIPHA	PLL Clock Driver
IPHAKHEJI YEDIVAYSI YENSIZA	48-TSSOP
UCHUNGECHUNGE	-
UKULINGANISWA - UKUFAKWA: OKUKHIPHAYO	1:10
UKUPAKISHA	Tube
IPHAKHEJI / ICALA	48-TFSOP (0.240", 6.10mm Width)
PLL	Yes with Bypass
OKUKHIPHAYO	Clock
AMANYE AMAGAMA	296-24143-5 CDCV857DGG-ND
UKUSHISA OKUSEBENZAYO	0°C ~ 85°C
INOMBOLO YAMATHAMBO	1
UHLOBO LOKUFAKA	Surface Mount
IZINGA LOKUZWELA UKUTHUTHA (MSL)	2 (1 Year)
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Lead free / RoHS Compliant
UKUFAKA	Clock
UKUVAMA - MAX	200MHz
UKUHLUKANISA / UKUPHINDA	No/No
UKUHLUKA - UKUFAKA: OKUKHIPHAYO	Yes/Yes
I-BASE PART NUMBER	CDCV857

Amathegi ahlobene

I- CDCV857DGG	Umsabalalisi we-CDCV857DGG	Umhlinzeki we-CDCV857DGG
Intengo ye-CDCV857DGG	Izithombe ze-CDCV857DGG	CDCV857DGG Image
Idatha ye-CDCV857DGG PDF	I-CDCV857DGG Landa iDatasheet	Idatha ye-CDCV857DGG
CDCV857DGG stock	Thenga i-CDCV857DGG	Thenga i- CDCV857DGG
I- CDCV857DGG	Umphekeli we-	Umsabalalisi we-

Imikhiqizo ehlobene

<p>CDCV857DGGRG4 Abakhiqizi: N/A Incazelo: IC SSTL-II PLL CLK-DRVR 48TSSOP Kukhona kusitoki: 5405 pcs</p> <p>RFQ</p>	<p>CDCVF111FNG4 Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:9 650MHZ 28PLCC Kukhona kusitoki: 5389 pcs</p> <p>RFQ</p>
<p>CDCV857DGGG4 Abakhiqizi: N/A Incazelo: IC SSTL-II PLL CLK-DRVR 48TSSOP Kukhona kusitoki: 4677 pcs</p> <p>RFQ</p>	<p>CDCV857BGQLR Abakhiqizi: N/A Incazelo: IC 2.5V PLL CLOCK DRVR 56-BGA Kukhona kusitoki: 4617 pcs</p> <p>RFQ</p>
<p>CDCV857BIDGGR Abakhiqizi: N/A Incazelo: IC SSTL-II PLL CLK-DRVR 48TSSOP Kukhona kusitoki: 16291 pcs</p> <p>RFQ</p>	<p>CDCV857BDGGRG4 Abakhiqizi: N/A Incazelo: IC SSTL-II PLL CLK-DRVR 48TSSOP Kukhona kusitoki: 22822 pcs</p> <p>RFQ</p>
<p>CDCVF111FNR Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:9 650MHZ 28PLCC Kukhona kusitoki: 7790 pcs</p> <p>RFQ</p>	<p>CDCV857BIDGGRG4 Abakhiqizi: N/A Incazelo: IC SSTL-II PLL CLK-DRVR 48TSSOP Kukhona kusitoki: 19369 pcs</p> <p>RFQ</p>
<p>CDCV857DGGR Abakhiqizi: N/A Incazelo: IC SSTL-II PLL CLK-DRVR 48-TSSOP Kukhona kusitoki: 5363 pcs</p> <p>RFQ</p>	<p>CDCV857BIDGGG4 Abakhiqizi: N/A Incazelo: IC SSTL-II PLL CLK-DRVR 48-TSSOP Kukhona kusitoki: 8726 pcs</p> <p>RFQ</p>
<p>CDCV857BIDGG Abakhiqizi: N/A Incazelo: IC SSTL-II PLL CLK-DRVR 48-TSSOP Kukhona kusitoki: 10910 pcs</p> <p>RFQ</p>	<p>CDCVF111FN Abakhiqizi: N/A Incazelo: IC CLK BUFFER 1:9 650MHZ 28PLCC Kukhona kusitoki: 6603 pcs</p> <p>RFQ</p>