




AVX Corporation

CP0603B1880AWTR

Inombolo Yengxenywe:	CP0603B1880AWTR
Umkhqizi / Umkhqizo:	AVX Corporation
Incazelo yomkhqizo	RF DIR COUPLER 1.85-1.91GHZ 0603
Amadokhumenti:	PDF CP0603B1880AWTR.pdf
Isimo se-RoHS	 Iqukethe ukuhola / RoHS okungavumelani
Umkhumbi ovela	i-Hong Kong
Ukuthunyelwa Kwendlela	DHL/Fedex/TNT/UPS/EMS

[ISICELO SOKUCAPHUNA](#)

Isithombe singabekwa. Bheka imininingwane yemininingwane yomkhqizo.













Imininingwane ye-CP0603B1880AWTR

INOMBOLO YENGXENYE	CP0603B1880AWTR
UMKHIQIZI	AVX Corporation
INCAZELO	RF DIR COUPLER 1.85-1.91GHZ 0603
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Iqukethe ukuhola / RoHS okungavumelani
ISHIDI LE-DATA	PDF CP0603B1880AWTR.pdf
IPHAKHEJI YEDIVAYISI YENSIZA	0603
UCHUNGECHUNGE	-
BUYISELA UKULAHLEKELWA	-33dB
AMANDLA - MAX	3W
UKUPAKISHA	Tape & Reel (TR)
IPHAKHEJI / ICALA	0603 (1608 Metric)
IZINGA LOKUZWELA UKUTHUTHA (MSL)	1 (Unlimited)
ISIKHATHI SESIKHATHI ESIYISIBONELO SOKUKHIQIZA	10 Weeks
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Contains lead / RoHS non-compliant
UKUHLUKANISWA	-29dB
UKUFELWA KOKUFAKIWE	0.3dB
UKUVAMA	1.85GHz ~ 1.91GHz
INCAZELO EPHELELE	RF Directional Coupler PCS 1.85GHz ~ 1.91GHz 17.5 ± 1dB 3W 0603 (1608 Metric)
FACT FACTOR	17.5 ± 1dB
UHLOBO LOMBHANGQWANA	Standard
IZICELO	PCS

Amathegi ahlobene

I-AVX Corporation CP0603B1880AWTR	Umsabalalisi we-CP0603B1880AWTR	Umhlinzeki we-CP0603B1880AWTR
Intengo ye-CP0603B1880AWTR	Izithombe ze-CP0603B1880AWTR	CP0603B1880AWTR Image
Idatha ye-CP0603B1880AWTR PDF	I-CP0603B1880AWTR Landa iDatasheet	Idatha ye-CP0603B1880AWTR
CP0603B1880AWTR stock	Thenga i-CP0603B1880AWTR	Thenga i-AVX Corporation CP0603B1880AWTR
I-AVX Corporation CP0603B1880AWTR	Umphekeli we-AVX Corporation	Umsabalalisi we-AVX Corporation
I-AVX Corporation CP0603B1880AWTR	I-AVX Corporation [MIL] CP0603B1880AWTR	

Imikhqizo ehlobene

 <p>CP0603B1880BWTR Abakhqizi: AVX Corporation Incazelo: RF DIR COUPLER 1.85-1.91GHZ 0603 Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>CP0603B1441CWTR Abakhqizi: AVX Corporation Incazelo: RF DIR COUPLER 1.429-1.453GHZ 0603 Kukhona kusitoki: Out stock</p> <p>RFQ</p>
 <p>CP0603B1950BWTR Abakhqizi: AVX Corporation Incazelo: RF DIR COUPLER 1.85-1.95GHZ 0603 Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>CP0603B1842BWTR Abakhqizi: AVX Corporation Incazelo: RF DIR COUPLER 1.805-1.88GHZ 0603 Kukhona kusitoki: Out stock</p> <p>RFQ</p>
 <p>CP0603B1960AWTR Abakhqizi: AVX Corporation Incazelo: RF DIR COUPLER 1.93-1.99GHZ 0603 Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>CP0603B1620AWTR Abakhqizi: AVX Corporation Incazelo: RF DIR COUPLER 1.62GHZ 0603 Kukhona kusitoki: Out stock</p> <p>RFQ</p>
 <p>CP0603B1960BWTR Abakhqizi: AVX Corporation Incazelo: RF DIR COUPLER 1.93-1.99GHZ 0603 Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>CP0603B0947CWTR Abakhqizi: AVX Corporation Incazelo: RF DIR COUPLER 935-960MHZ 0603 Kukhona kusitoki: Out stock</p> <p>RFQ</p>
 <p>CP0603B1747CWTR Abakhqizi: AVX Corporation Incazelo: RF DIR COUPLER 1.71-1.785GHZ 0603 Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>CP0603B1842CWTR Abakhqizi: AVX Corporation Incazelo: RF DIR COUPLER 1.805-1.88GHZ 0603 Kukhona kusitoki: Out stock</p> <p>RFQ</p>
 <p>CP0603B1950AW Abakhqizi: AVX Corporation Incazelo: RF DIR COUPLER 1.95GHZ 0603 Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>CP0603B1950CW Abakhqizi: AVX Corporation Incazelo: RF DIR COUPLER 1.95GHZ 0603 Kukhona kusitoki: Out stock</p> <p>RFQ</p>