



IDT (Integrated Device Technology)


Technology



IDT2308A-5HDC

Inombolo Yengxenywe:
 Umkhiqizo / Umkhiqizo:
 Incazelo yomkhiqizo
 Amadokhumenti:
 Isimo se-RoHS
 Umkhumbi ovela
 Ukuthunyelwa Kwendlela

IDT2308A-5HDC
 IDT (Integrated Device Technology)
 IC CLOCK MULT ZD HI DRV 16-SOIC

 Iqukethe ukuhola / RoHS okungavumelani
 i-Hong Kong
 DHL/Fedex/TNT/UPS/EMS

ISICELO SOKUCAPHUNA

Isithombe singabekwa. Bheka imininingwane yemininingwane yomkhiqizo.













Imininingwane ye-IDT2308A-5HDC

INOMBOLO YENGXENYE	IDT2308A-5HDC
UMKHIQIZI	IDT (Integrated Device Technology)
INCAZELO	IC CLOCK MULT ZD HI DRV 16-SOIC
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Iqukethe ukuhola / RoHS okungavumelani
ISHIDI LE-DATA	
I-VOLTAGE - SUPPLY	3 V ~ 3.6 V
THAYIPHA	Multiplier, Zero Delay Buffer
IPHAKHEJI YEDIVAYSI YENSIZA	16-SOIC
UCHUNGECHUNGE	-
UKULINGANISWA - UKUFAKWA: OKUKHIPHAYO	1:8
UKUPAKISHA	Tube
IPHAKHEJI / ICALA	16-SOIC (0.154", 3.90mm Width)
PLL	Yes with Bypass
OKUKHIPHAYO	LVTTTL
AMANYE AMAGAMA	2308A-5HDC
UKUSHISA OKUSEBENZAYO	0°C ~ 70°C
INOMBOLO YAMATHAMBO	1
UHLOBO LOKUFAKA	Surface Mount
IZINGA LOKUZWELA UKUTHUTHA (MSL)	1 (Unlimited)
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Contains lead / RoHS non-compliant
UKUFAKA	LVTTTL
UKUVAMA - MAX	133MHz
UKUHLUKANISA / UKUPHINDA	-
UKUHLUKA - UKUFAKA: OKUKHIPHAYO	No/No
I-BASE PART NUMBER	IDT2308-5

Amathegi ahlobene

I-IDT (Integrated Device Technology) IDT2308A-5HDC	Umsabalalisi we-IDT2308A-5HDC	Umhlinzeki we-IDT2308A-5HDC
Intengo ye-IDT2308A-5HDC	Izithombe ze-IDT2308A-5HDC	IDT2308A-5HDC Image
Idatha ye-IDT2308A-5HDC PDF	I-IDT2308A-5HDC Landa iDatasheet	Idatha ye-IDT2308A-5HDC
IDT2308A-5HDC stock	Thenga i-IDT2308A-5HDC	Thenga i-IDT (Integrated Device Technology) IDT2308A-5HDC
I-IDT (Integrated Device Technology) IDT2308A-5HDC	Umphekeli we-IDT (Integrated Device Technology)	Umsabalalisi we-IDT (Integrated Device Technology)
I-IDT (Integrated Device Technology) IDT2308A-5HDC	I-IDT IDT2308A-5HDC	I-IDT (Integrated Device Technology) IDT2308A-5HDC
I-IDT, Integrated Device Technology Inc IDT2308A-5HDC	I-Integrated Device Technology (IDT) IDT2308A-5HDC	

Imikhiqizo ehlobene

 <p>IDT2308A-4DCI8 Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLOCK MULT ZD HI DRV 16-SOIC Kukhona kusitoki: Out stock RFQ</p>	 <p>IDT2308A-4DCI Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLOCK MULT ZD STD DRV 16-SOIC Kukhona kusitoki: Out stock RFQ</p>
 <p>IDT2308A-5HDCI Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLOCK MULT ZD HI DRV 16-SOIC Kukhona kusitoki: Out stock RFQ</p>	 <p>IDT2308A-3DCI8 Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLOCK MULT ZD STD DRV 16-SOIC Kukhona kusitoki: Out stock RFQ</p>
 <p>IDT2308A-3DCI Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLOCK MULT ZD STD DRV 16-SOIC Kukhona kusitoki: Out stock RFQ</p>	 <p>IDT2308A-5HDC8 Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLOCK MULT ZD HI DRV 16-SOIC Kukhona kusitoki: Out stock RFQ</p>
 <p>IDT2308A-5HDCI8 Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLOCK MULT ZD HI DRV 16-SOIC Kukhona kusitoki: Out stock RFQ</p>	 <p>IDT2308A-4DC8 Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLOCK MULT ZD STD DRV 16-SOIC Kukhona kusitoki: Out stock RFQ</p>
 <p>IDT2308A-5HPG Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLOCK MULT ZD HI DRV 16-TSSOP Kukhona kusitoki: Out stock RFQ</p>	 <p>IDT2308A-4DC Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLOCK MULT ZD STD DRV 16-SOIC Kukhona kusitoki: Out stock RFQ</p>
 <p>IDT2308A-5HPGI Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLOCK MULT ZD HI DRV 16-TSSOP Kukhona kusitoki: Out stock RFQ</p>	 <p>IDT2308A-5HPG8 Abakhiqizi: IDT (Integrated Device Technology) Incazelo: IC CLOCK MULT ZD HI DRV 16-TSSOP Kukhona kusitoki: Out stock RFQ</p>