




Micrel / Microchip Technology

SY89830UK4I

Inombolo Yengxenywe:
 Umkhiqizi / Umkhiqizo:
 Incazelo yomkhiqizo
 Amadokhumenti:
 Isimo se-RoHS
 Umkhumbi ovela
 Ukuthunyelwa Kwendlela

SY89830UK4I
 Micrel / Microchip Technology
 IC CLK BUFFER 2:4 2.5GHZ 16TSSOP
[PDF SY89830UK4I.pdf](#)
 Iqukethe ukuhola / RoHS okungavumelani
 i-Hong Kong
 DHL/Fedex/TNT/UPS/EMS



Isithombe singabekwa. Bheka imininingwane yemininingwane yomkhiqizo.

ISICELO SOKUCAPHUNA













Imininingwane ye-SY89830UK4I

INOMBOLO YENGXENYE	SY89830UK4I
UMKHIQIZI	Micrel / Microchip Technology
INCAZELO	IC CLK BUFFER 2:4 2.5GHZ 16TSSOP
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Iqukethe ukuhola / RoHS okungavumelani
ISHIDI LE-DATA	PDF SY89830UK4I.pdf
I-VOLTAGE - SUPPLY	2.375 V ~ 5.5 V
THAYIPHA	Fanout Buffer (Distribution), Multiplexer
IPHAKHEJI YEDIVAYISI YENSIZA	16-TSSOP
UCHUNGECHUNGE	Precision Edge®
UKULINGANISWA - UKUFAKWA: OKUKHIPHAYO	2:4
UKUPAKISHA	Tube
IPHAKHEJI / ICALE	16-TSSOP (0.173", 4.40mm Width)
OKUKHIPHAYO	LVECL, LVPECL
UKUSHISA OKUSEBENZAYO	-40°C ~ 85°C
INOMBOLO YAMATHAMBO	1
UHLOBO LOKUFAKA	Surface Mount
IZINGA LOKUZWELA UKUTHUTHA (MSL)	1 (Unlimited)
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Contains lead / RoHS non-compliant
UKUFAKA	HSTL, LVECL, LVPECL
UKUVAMA - MAX	2.5GHz
UKUHLUKA - UKUFAKA: OKUKHIPHAYO	Yes/Yes
INCAZELO EPHELELE	Clock Fanout Buffer (Distribution), Multiplexer IC 2:4 2.5GHz 16-TSSOP (0.173", 4.40mm Width)
I-BASE PART NUMBER	SY89830

Amathegi ahlobene

I-Micrel / Microchip Technology SY89830UK4I	Umsabalalisi we-SY89830UK4I	Umhlinzeki we-SY89830UK4I
Intengo ye-SY89830UK4I	Izithombe ze-SY89830UK4I	SY89830UK4I Image
Idatha ye-SY89830UK4I PDF	I-SY89830UK4I Landa iDatasheet	Idatha ye-SY89830UK4I
SY89830UK4I stock	Thenga i-SY89830UK4I	Thenga i-Micrel / Microchip Technology SY89830UK4I
I-Micrel / Microchip Technology SY89830UK4I	Umphakeli we-Micrel / Microchip Technology	Umsabalalisi we-Micrel / Microchip Technology
I-Micrel / Microchip Technology SY89830UK4I	I-Microchip Technology SY89830UK4I	I-Roving Networks / Microchip Technology SY89830UK4I

Imikhiqizo ehlobene

 <p>SY89828LHY-TR Abakhiqizi: Micrel / Microchip Technology Incazelo: IC CLK BUFFER 2:10 1GHZ 64TQFP Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>SY89829UHY Abakhiqizi: Micrel / Microchip Technology Incazelo: IC CLK BUFFER 2:10 2GHZ 64TQFP Kukhona kusitoki: 67 pcs</p> <p>RFQ</p>
 <p>SY89829UHI Abakhiqizi: Micrel / Microchip Technology Incazelo: IC CLK BUFFER 2:10 2GHZ 64TQFP Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>SY89831UMI Abakhiqizi: Micrel / Microchip Technology Incazelo: IC CLK BUFFER 1:4 2GHZ 16MLF Kukhona kusitoki: Out stock</p> <p>RFQ</p>
 <p>SY89829UHY-TR Abakhiqizi: Micrel / Microchip Technology Incazelo: IC CLK BUFFER 2:10 2GHZ 64TQFP Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>SY89830UK4G-TR Abakhiqizi: Micrel / Microchip Technology Incazelo: IC CLK BUFFER 2:4 2.5GHZ 16TSSOP Kukhona kusitoki: Out stock</p> <p>RFQ</p>
 <p>SY89830UK4I-TR Abakhiqizi: Micrel / Microchip Technology Incazelo: IC CLK BUFFER 2:4 2.5GHZ 16TSSOP Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>SY89831UMI-TR Abakhiqizi: Micrel / Microchip Technology Incazelo: IC CLK BUFFER 1:4 2GHZ 16MLF Kukhona kusitoki: Out stock</p> <p>RFQ</p>
 <p>SY89831UMG Abakhiqizi: Micrel / Microchip Technology Incazelo: IC CLK BUFFER 1:4 2GHZ 16MLF Kukhona kusitoki: 486 pcs</p> <p>RFQ</p>	 <p>SY89831UMG-TR Abakhiqizi: Micrel / Microchip Technology Incazelo: IC CLK BUFFER 1:4 2GHZ 16MLF Kukhona kusitoki: 998 pcs</p> <p>RFQ</p>
 <p>SY89832UMG Abakhiqizi: Micrel / Microchip Technology Incazelo: IC CLK BUFFER 1:4 2.5GHZ 16MLF Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>SY89830UK4G Abakhiqizi: Micrel / Microchip Technology Incazelo: IC CLK BUFFER 2:4 2.5GHZ 16TSSOP Kukhona kusitoki: Out stock</p> <p>RFQ</p>