

N/A

**CDCV304PWRG4**

Inombolo Yengxenywe:

CDCV304PWRG4

Umkhqizi / Umkhqizo:

N/A

Incazelo yomkhqizo

IC CLK BUFFER 1:4 200MHZ 8TSSOP

Amadokhumenti:

Isimo se-RoHS

 Qondisa mahhala / i-RoHS Compliant

Umkhumbi ovela

i-Hong Kong

Ukuthunyelwa Kwendlela

DHL/Fedex/TNT/UPS/EMS



No Picture

ISICELO SOKUCAPHUNA

Isithombe singabekwa. Bheka imininingwane yemininingwane yomkhqizo.













## Imininingwane ye-CDCV304PWRG4

INOMBOLO YENGXENYE	CDCV304PWRG4
UMKHIQIZI	N/A
INCAZELO	IC CLK BUFFER 1:4 200MHZ 8TSSOP
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Qondisa mahhala / i-RoHS Compliant
ISHIDI LE-DATA	
I-VOLTAGE - SUPPLY	2.3 V ~ 3.6 V
THAYIPHA	Fanout Buffer (Distribution)
IPHAKHEJI YEDIVAYSI YENSIZA	8-TSSOP
UCHUNGECHUNGE	-
UKULINGANISWA - UKUFAKWA: OKUKHIPHAYO	1:4
UKUPAKISHA	Tape & Reel (TR)
IPHAKHEJI / ICALA	8-TSSOP (0.173", 4.40mm Width)
OKUKHIPHAYO	LVTTTL
AMANYE AMAGAMA	296-35899-2 CDCV304PWRG4-ND
UKUSHISA OKUSEBENZAYO	-40°C ~ 85°C
INOMBOLO YAMATHAMBO	1
UHLOBO LOKUFAKA	Surface Mount
IZINGA LOKUZWELA UKUTHUTHA (MSL)	1 (Unlimited)
ISIKHATHI SESIKHATHI ESIYISIBONELO SOKUKHIQIZA	20 Weeks
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Lead free / RoHS Compliant
UKUFAKA	LVTTTL
UKUVAMA - MAX	200MHz
UKUHLUKA - UKUFAKA: OKUKHIPHAYO	No/No
INCAZELO EPHELELE	Clock Fanout Buffer (Distribution) IC 1:4 200MHz 8-TSSOP (0.173", 4.40mm Width)
I-BASE PART NUMBER	CDCV304

## Amathegi ahlobene

I- CDCV304PWRG4	Umsabalalisi we-CDCV304PWRG4	Umhlinzeki we-CDCV304PWRG4
Intengo ye-CDCV304PWRG4	Izithombe ze-CDCV304PWRG4	CDCV304PWRG4 Image
Idatha ye-CDCV304PWRG4 PDF	I-CDCV304PWRG4 Landa iDatasheet	Idatha ye-CDCV304PWRG4
CDCV304PWRG4 stock	Thenga i-CDCV304PWRG4	Thenga i- CDCV304PWRG4
I- CDCV304PWRG4	Umphakeli we-	Umsabalalisi we-

## Imikhqizo ehlobene

 <p><b>CDCV850IDGG</b> Abakhqizi: N/A Incazelo: IC PLL CLOCK DRVR 2.5V 48-TSSOP Kukhona kusitoki: 23791 pcs</p> <p><b>RFQ</b></p>	 <p><b>CDCUN1208LPEVM</b> Abakhqizi: N/A Incazelo: EVAL MODULE FOR CDCUN1208LP Kukhona kusitoki: 463 pcs</p> <p><b>RFQ</b></p>
 <p><b>CDCV304PWR</b> Abakhqizi: N/A Incazelo: IC PLL CLOCK BUFFER 1:4 200MHZ 8TSSOP Kukhona kusitoki: 53713 pcs</p> <p><b>RFQ</b></p>	 <p><b>CDCV304PWG4</b> Abakhqizi: N/A Incazelo: IC CLK BUFFER 1:4 200MHZ 8TSSOP Kukhona kusitoki: 58720 pcs</p> <p><b>RFQ</b></p>
 <p><b>CDCV850DGGG4</b> Abakhqizi: N/A Incazelo: IC PLL CLOCK DRVR 2.5V 48TSSOP Kukhona kusitoki: 19469 pcs</p> <p><b>RFQ</b></p>	 <p><b>CDCV304PW</b> Abakhqizi: N/A Incazelo: IC CLK BUFFER 1:4 200MHZ 8TSSOP Kukhona kusitoki: 55452 pcs</p> <p><b>RFQ</b></p>
 <p><b>CDCUN1208LPRHBT</b> Abakhqizi: N/A Incazelo: IC CLK BUFFER 2:8 400MHZ 32QFN Kukhona kusitoki: 15468 pcs</p> <p><b>RFQ</b></p>	 <p><b>CDCV850DGGRG4</b> Abakhqizi: N/A Incazelo: IC PLL CLOCK DRVR 2.5V 48TSSOP Kukhona kusitoki: 27994 pcs</p> <p><b>RFQ</b></p>
 <p><b>CDCV304TPWREP</b> Abakhqizi: N/A Incazelo: IC CLK BUFFER 1:4 200MHZ 8TSSOP Kukhona kusitoki: 21714 pcs</p> <p><b>RFQ</b></p>	 <p><b>CDCV850DGG</b> Abakhqizi: N/A Incazelo: IC PLL CLOCK DRVR 2.5V 48-TSSOP Kukhona kusitoki: 22414 pcs</p> <p><b>RFQ</b></p>
 <p><b>CDCV850DGGR</b> Abakhqizi: N/A Incazelo: IC PLL CLOCK DRVR 2.5V 48-TSSOP Kukhona kusitoki: 26517 pcs</p> <p><b>RFQ</b></p>	 <p><b>CDCUN1208LPRHBR</b> Abakhqizi: N/A Incazelo: IC CLK BUFFER 2:8 400MHZ 32QFN Kukhona kusitoki: 15812 pcs</p> <p><b>RFQ</b></p>