



SICK

DGS35-YK402048

Inombolo Yengxenywe:

DGS35-YK402048

Umkhiqizi / Umkhiqizo:

SICK

Incazelo yomkhiqizo

ROTARY ENCODR INCREMENT 2048PPR

Amadokhumenti:

Umkhumbi ovela

i-Hong Kong

Ukuthunyelwa Kwendlela

DHL/Fedex/TNT/UPS/EMS


[ISICELO SOKUCAPHUNA](#)

Isithombe singabekwa. Bheka imininingwane yemininingwane yomkhiqizo.













Imininingwane ye-DGS35-YK402048

INOMBOLO YENGXENYE	DGS35-YK402048
UMKHIQIZI	SICK
INCAZELO	ROTARY ENCODR INCREMENT 2048PPR
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	
ISHIDI LE-DATA	
I-VOLTAGE - SUPPLY	5V
ISITAYELA SOKUQEDA	Connector
UCHUNGECHUNGE	-
UKUPHILA OKUJIKHEZAYO (AMA-CYCLES MIN)	-
AMAPULISI NGE-REVOLUTION	2048
UHLOBO LOKUPHUMA	-
AMANYE AMAGAMA	1065096
ISIFUNDO	User Selectable
UHLOBO LOKUFAKA	Chassis Mount
ISIKHATHI SESIKHATHI ESIYISIBONELO SOKUKHIQIZA	3 Weeks
UHLOBO LWEKHOWUDI	Incremental
UKUZETHEMBA	No
YAKHELWE KU-SWITCH	No
UHLOBO LWE-ACTUATOR	Hole for Shaft

Amathegi ahlobene

I-SICK DGS35-YK402048	Umsabalalisi we-DGS35-YK402048	Umhlinzeki we-DGS35-YK402048
Intengo ye-DGS35-YK402048	Izithombe ze-DGS35-YK402048	DGS35-YK402048 Image
Idatha ye-DGS35-YK402048 PDF	I-DGS35-YK402048 Landa iDatasheet	Idatha ye-DGS35-YK402048
DGS35-YK402048 stock	Thenga i-DGS35-YK402048	Thenga i-SICK DGS35-YK402048
I-SICK DGS35-YK402048	Umphekeli we-SICK	Umsabalalisi we-SICK
I-SICK DGS35-YK402048		

Imikhiqizo ehlobene

 <p>DGS35-YHK05000 Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 5000PPR Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>DGS35-YL202048 Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 2048PPR Kukhona kusitoki: Out stock</p> <p>RFQ</p>
 <p>DGS35-YK216384 Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 16384PPR Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>DGS35-YH401024 Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 1024PPR Kukhona kusitoki: Out stock</p> <p>RFQ</p>
 <p>DGS35-YKN16384 Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 16384PPR Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>DGS35-YL416384 Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 16384PPR Kukhona kusitoki: Out stock</p> <p>RFQ</p>
 <p>DGS35-YK201024 Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 1024PPR Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>DGS35-YKK16384 Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 16384PPR Kukhona kusitoki: Out stock</p> <p>RFQ</p>
 <p>DGS35-YKK02048 Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 2048PPR Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>DGS35-YK410000 Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 10000PPR Kukhona kusitoki: Out stock</p> <p>RFQ</p>
 <p>DGS35-YHK02500 Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 2500PPR Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>DGS35-YHN10000 Abakhiqizi: SICK Incazelo: ROTARY ENCODR INCREMENT 10000PPR Kukhona kusitoki: Out stock</p> <p>RFQ</p>

I-Copyright © 2020 Distributor Ethembekile Yezingxenywe Ze-elektronikhi - Ocean-Components.com

Imeyili: I-Info@Ocean-Components.com

Ikheli: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

