






42-CBSA-1.25X3.5X0.4

| | |
|------------------------|--|
| Inombolo Yengxenywe: | 42-CBSA-1.25X3.5X0.4 |
| Umkhiqizi / Umkhiqizo: | Leader Tech Inc. |
| Incazelo yomkhiqizo | 42 SERIES CBS SHIELD ASSEMBLY |
| Amadokhumenti: |  42-CBSA-1.25X3.5X0.4.pdf |
| Isimo se-RoHS |  Qondisa mahhala / i-RoHS Compliant |
| Umkhumbi ovela | i-Hong Kong |
| Ukuthunyelwa Kwendlela | DHL/Fedex/TNT/UPS/EMS |

ISICELO SOKUCAPHUNA

Isithombe singabekwa. Bheka iminingwane yeminingwane yomkhiqizo.













Imininingwane ye-42-CBSA-1.25X3.5X0.4

| | |
|--|--|
| INOMBOLO YENGXENYE | 42-CBSA-1.25X3.5X0.4 |
| UMKHIQIZI | Leader Tech Inc. |
| INCAZELO | 42 SERIES CBS SHIELD ASSEMBLY |
| ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS | Qondisa mahhala / i-RoHS Compliant |
| ISHIDI LE-DATA |  42-CBSA-1.25X3.5X0.4.pdf |
| UBUBANZI - KONKE | 1.250" (31.75mm) |
| UKUPHUMULA | Vent Holes in Pattern |
| THAYIPHA | Shield, 2-Piece |
| UCHUNGECHUNGE | 40-CBS |
| UKUPAKISHA | Bulk |
| UHLOBO LOKUFAKA | Through Hole |
| IZINGA LOKUZWELA UKUTHUTHA (MSL) | 1 (Unlimited) |
| ISIKHATHI SESIKHATHI ESIYISIBONELO SOKUKHIQIZA | 3 Weeks |
| UBUDE - KONKE | 3.500" (88.90mm) |
| ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS | Lead free / RoHS Compliant |
| UKUPHAKAMA - KONKE | 0.400" (10.16mm) |
| INCAZELO EPHELELE | RF Shield Shield, 2-Piece 1.250" (31.75mm) X 3.500" (88.90mm) Vent Holes in Pattern Through Hole |

Amathegi ahlobene

| | | |
|---|--|--|
| I-Leader Tech Inc. 42-CBSA-1.25X3.5X0.4 | Umsabalalisi we-42-CBSA-1.25X3.5X0.4 | Umhlinzeki we-42-CBSA-1.25X3.5X0.4 |
| Intengo ye-42-CBSA-1.25X3.5X0.4 | Izithombe ze-42-CBSA-1.25X3.5X0.4 | 42-CBSA-1.25X3.5X0.4 Image |
| Idatha ye-42-CBSA-1.25X3.5X0.4 PDF | I-42-CBSA-1.25X3.5X0.4 Landa iDatashet | Idatha ye-42-CBSA-1.25X3.5X0.4 |
| 42-CBSA-1.25X3.5X0.4 stock | Thenga i-42-CBSA-1.25X3.5X0.4 | Thenga i-Leader Tech Inc. 42-CBSA-1.25X3.5X0.4 |
| I-Leader Tech Inc. 42-CBSA-1.25X3.5X0.4 | Umpakeli we-Leader Tech Inc. | Umsabalalisi we-Leader Tech Inc. |
| I-Leader Tech Inc. 42-CBSA-1.25X3.5X0.4 | | |

Imikhiqizo ehlobene

| | |
|---|--|
|  <p>42-CBSA-1.25X5.0X0.4 Abakhiqizi: Leader Tech Inc. Incazelo: 42 SERIES CBS SHIELD ASSEMBLY Kukhona kusitoki: Out stock</p> <p>RFQ</p> |  <p>42-CBSA-1.25X3.75X0.4 Abakhiqizi: Leader Tech Inc. Incazelo: 42 SERIES CBS SHIELD ASSEMBLY Kukhona kusitoki: Out stock</p> <p>RFQ</p> |
|  <p>42-CBSA-1.25X2.25X0.4 Abakhiqizi: Leader Tech Inc. Incazelo: 42 SERIES CBS SHIELD ASSEMBLY Kukhona kusitoki: Out stock</p> <p>RFQ</p> |  <p>42-CBSA-1.25X4.0X0.4 Abakhiqizi: Leader Tech Inc. Incazelo: 42 SERIES CBS SHIELD ASSEMBLY Kukhona kusitoki: Out stock</p> <p>RFQ</p> |
|  <p>42-CBSA-1.25X4.75X0.4 Abakhiqizi: Leader Tech Inc. Incazelo: 42 SERIES CBS SHIELD ASSEMBLY Kukhona kusitoki: Out stock</p> <p>RFQ</p> |  <p>42-CBSA-1.25X2.0X0.4 Abakhiqizi: Leader Tech Inc. Incazelo: 42 SERIES CBS SHIELD ASSEMBLY Kukhona kusitoki: Out stock</p> <p>RFQ</p> |
|  <p>42-CBSA-1.25X3.0X0.4 Abakhiqizi: Leader Tech Inc. Incazelo: 42 SERIES CBS SHIELD ASSEMBLY Kukhona kusitoki: Out stock</p> <p>RFQ</p> |  <p>42-CBSA-1.25X2.75X0.4 Abakhiqizi: Leader Tech Inc. Incazelo: 42 SERIES CBS SHIELD ASSEMBLY Kukhona kusitoki: Out stock</p> <p>RFQ</p> |
|  <p>42-CBSA-1.25X4.5X0.4 Abakhiqizi: Leader Tech Inc. Incazelo: 42 SERIES CBS SHIELD ASSEMBLY Kukhona kusitoki: Out stock</p> <p>RFQ</p> |  <p>42-CBSA-1.25X3.25X0.4 Abakhiqizi: Leader Tech Inc. Incazelo: 42 SERIES CBS SHIELD ASSEMBLY Kukhona kusitoki: Out stock</p> <p>RFQ</p> |
|  <p>42-CBSA-1.25X2.5X0.4 Abakhiqizi: Leader Tech Inc. Incazelo: 42 SERIES CBS SHIELD ASSEMBLY Kukhona kusitoki: Out stock</p> <p>RFQ</p> |  <p>42-CBSA-1.25X4.25X0.4 Abakhiqizi: Leader Tech Inc. Incazelo: 42 SERIES CBS SHIELD ASSEMBLY Kukhona kusitoki: Out stock</p> <p>RFQ</p> |