




25BR22-G-1-16C

Inombolo Yengxenywe:	25BR22-G-1-16C
Umkhqizi / Umkhqizo:	Grayhill, Inc.
Incazelo yomkhqizo	ROTARY ENCODER MECHANICAL 16PPR
Amadokhumenti:	25BR22-G-1-16C.pdf
Isimo se-RoHS	 Qondisa mahhala / i-RoHS Compliant
Umkhumbi ovela	i-Hong Kong
Ukuthunyelwa Kwendlela	DHL/Fedex/TNT/UPS/EMS

ISICELO SOKUCAPHUNA

Isithombe singabekwa. Bheka imininingwane yemininingwane yomkhqizo.













Imininingwane ye-25BR22-G-1-16C

INOMBOLO YENGXENYE	25BR22-G-1-16C
UMKHIQIZI	Grayhill, Inc.
INCAZELO	ROTARY ENCODER MECHANICAL 16PPR
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Qondisa mahhala / i-RoHS Compliant
ISHIDI LE-DATA	25BR22-G-1-16C.pdf
I-VOLTAGE - SUPPLY	-
ISITAYELA SOKUQEDA	PC Pin
UCHUNGECHUNGE	25
UKUPHILA OKUJIKELAZAYO (AMA-CYCLES MIN)	50K
AMAPULISI NGE-REVOLUTION	16
UHLOBO LOKUPHUMA	Gray Code (Absolute)
AMANYE AMAGAMA	25BR22G116C
ISIFUNDO	Right Angle
UHLOBO LOKUFAKA	PCB, Through Hole
IZINGA LOKUZWELA UKUTHUTHA (MSL)	1 (Unlimited)
ISIKHATHI SESIKHATHI ESIYISIBONELO SOKUKHIQIZA	8 Weeks
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Lead free / RoHS Compliant
UHLOBO LWEKHOWUDI	Mechanical
UKUZETHEMBA	No
YAKHELWE KU-SWITCH	No
UHLOBO LWE-ACTUATOR	1/4" Dia Flatted End

Amathegi ahlobene

I-Grayhill, Inc. 25BR22-G-1-16C	Umsabalalisi we-25BR22-G-1-16C	Umhlinzeki we-25BR22-G-1-16C
Intengo ye-25BR22-G-1-16C	Izithombe ze-25BR22-G-1-16C	25BR22-G-1-16C Image
Idatha ye-25BR22-G-1-16C PDF	I-25BR22-G-1-16C Landa iDatasheet	Idatha ye-25BR22-G-1-16C
25BR22-G-1-16C stock	Thenga i-25BR22-G-1-16C	Thenga i-Grayhill, Inc. 25BR22-G-1-16C
I-Grayhill, Inc. 25BR22-G-1-16C	Umphekeli we-Grayhill, Inc.	Umsabalalisi we-Grayhill, Inc.
I-Grayhill, Inc. 25BR22-G-1-16C	I-Grayhill Inc. 25BR22-G-1-16C	

Imikhiqizo ehlobene

 <p>25BR18-G-1-20C Abakhiqizi: Grayhill, Inc. Incazelo: ROTARY ENCODER MECHANICAL 20PPR Kukhona kusitoki: 3006 pcs</p> <p>RFQ</p>	 <p>25BR22-B-1-16C Abakhiqizi: Grayhill, Inc. Incazelo: ROTARY ENCODER MECHANICAL 16PPR Kukhona kusitoki: 2582 pcs</p> <p>RFQ</p>
 <p>25BR22-B-1-16F Abakhiqizi: Grayhill, Inc. Incazelo: ROTARY ENCODER MECHANICAL 16PPR Kukhona kusitoki: 3080 pcs</p> <p>RFQ</p>	 <p>25BR22-B-1-06 Abakhiqizi: Grayhill, Inc. Incazelo: ROTARY ENCODER MECHANICAL 16PPR Kukhona kusitoki: 1864 pcs</p> <p>RFQ</p>
 <p>25BSF22-B-1-16F Abakhiqizi: Grayhill, Inc. Incazelo: ROTARY ENCODER MECHANICAL 16PPR Kukhona kusitoki: 2702 pcs</p> <p>RFQ</p>	 <p>25BR22-B-1-09 Abakhiqizi: Grayhill, Inc. Incazelo: ROTARY ENCODER MECHANICAL 16PPR Kukhona kusitoki: 2430 pcs</p> <p>RFQ</p>
 <p>25BR18-G-1-20F Abakhiqizi: Grayhill, Inc. Incazelo: ROTARY ENCODER MECHANICAL 20PPR Kukhona kusitoki: 2745 pcs</p> <p>RFQ</p>	 <p>25BR400DVI-EVK Abakhiqizi: N/A Incazelo: BOARD EVALUATION FOR DSBR400 Kukhona kusitoki: 5557 pcs</p> <p>RFQ</p>
 <p>25BSF22-B-1-16C Abakhiqizi: Grayhill, Inc. Incazelo: ROTARY ENCODER MECHANICAL 16PPR Kukhona kusitoki: 2429 pcs</p> <p>RFQ</p>	 <p>25BSF22-Q-1-16F Abakhiqizi: Grayhill, Inc. Incazelo: ROTARY ENCODER MECHANICAL 16PPR Kukhona kusitoki: 3097 pcs</p> <p>RFQ</p>
 <p>25BR22-Q-1-16C Abakhiqizi: Grayhill, Inc. Incazelo: ROTARY ENCODER MECHANICAL 16PPR Kukhona kusitoki: 2886 pcs</p> <p>RFQ</p>	 <p>25BSF15-Q-1-24C Abakhiqizi: Grayhill, Inc. Incazelo: ROTARY ENCODER MECHANICAL 24PPR Kukhona kusitoki: 2266 pcs</p> <p>RFQ</p>