






ADI (Analog Devices, Inc.)

110227-HMC509LP5


Inombolo Yengxenywe:
 Umkhiqizi / Umkhiqizo:
 Incazelo yomkhiqizo
 Amadokhumenti:
 Isimo se-RoHS
 Umkhumbi ovela
 Ukuthunyelwa Kwendlela

110227-HMC509LP5
 ADI (Analog Devices, Inc.)
 BOARD EVAL HMC509LP5E
 110227-HMC509LP5.pdf
 Qondisa mahhala / i-RoHS Compliant
 i-Hong Kong
 DHL/Fedex/TNT/UPS/EMS


[ISICELO SOKUCAPHUNA](#)

Isithombe singabekwa. Bheka imininingwane yemininingwane yomkhiqizo.













Imininingwane ye-110227-HMC509LP5

INOMBOLO YENGXENYE	110227-HMC509LP5
UMKHIQIZI	ADI (Analog Devices, Inc.)
INCAZELO	BOARD EVAL HMC509LP5E
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Qondisa mahhala / i-RoHS Compliant
ISHIDI LE-DATA	 110227-HMC509LP5.pdf
THAYIPHA	Voltage Controlled Oscillator (VCO)
OKUQUKETHWE OKUNIKEZIWE	Board(s)
UCHUNGECHUNGE	-
AMANYE AMAGAMA	110227-HMC509LP5-ND 1127-2063
IZINGA LOKUZWELA UKUTHUTHA (MSL)	1 (Unlimited)
ISIMO SAMAHHALA SENDAWO / ISIMO SE-ROHS	Lead free / RoHS Compliant
UKUVAMA	7.8GHz ~ 8.8GHz
UKUSETSHENZISWA NEMIKHIQIZO / EHLOBENE	HMC509LP5
I-BASE PART NUMBER	HMC509

Amathegi ahlobene

I-ADI (Analog Devices, Inc.) 110227-HMC509LP5	Umsabalalisi we-110227-HMC509LP5	Umhlinzeki we-110227-HMC509LP5
Intengo ye-110227-HMC509LP5	Izithombe ze-110227-HMC509LP5	110227-HMC509LP5 Image
Idatha ye-110227-HMC509LP5 PDF	I-110227-HMC509LP5 Landa iDatasheet	Idatha ye-110227-HMC509LP5
110227-HMC509LP5 stock	Thenga i-110227-HMC509LP5	Thenga i-ADI (Analog Devices, Inc.) 110227-HMC509LP5
I-ADI (Analog Devices, Inc.) 110227-HMC509LP5	Umphekeli we-ADI (Analog Devices, Inc.)	Umsabalalisi we-ADI (Analog Devices, Inc.)
I-ADI (Analog Devices, Inc.) 110227-HMC509LP5	I-AD 110227-HMC509LP5	I-ADI (Analog Devices, Inc.) 110227-HMC509LP5
I-Analog Devices Inc. 110227-HMC509LP5	I-Analog Devices, Inc. 110227-HMC509LP5	

Imikhiqizo ehlobene

 <p>110227-HMC513LP5 Abakhiqizi: ADI (Analog Devices, Inc.) Incazelo: BOARD EVAL HMC513LP5E Kukhona kusitoki: 2 pcs</p> <p>RFQ</p>	 <p>1102267-2 Abakhiqizi: Agastat Relays / TE Connectivity Incazelo: CONN HOOD TOP ENTRY SZ4 PG16 Kukhona kusitoki: Out stock</p> <p>RFQ</p>
 <p>110227-HMC507LP5 Abakhiqizi: ADI (Analog Devices, Inc.) Incazelo: BOARD EVAL HMC507LP5E Kukhona kusitoki: 1 pcs</p> <p>RFQ</p>	 <p>110227-HMC515LP5 Abakhiqizi: ADI (Analog Devices, Inc.) Incazelo: BOARD EVAL HMC515LP5E Kukhona kusitoki: 1 pcs</p> <p>RFQ</p>
 <p>110227-HMC508LP5 Abakhiqizi: ADI (Analog Devices, Inc.) Incazelo: BOARD EVAL HMC508LP5E Kukhona kusitoki: 4 pcs</p> <p>RFQ</p>	 <p>1102261001 Abakhiqizi: Weidmuller Incazelo: RELAY GEN PURPOSE SPST 3A 230V Kukhona kusitoki: Out stock</p> <p>RFQ</p>
 <p>1102246-6 Abakhiqizi: Agastat Relays / TE Connectivity Incazelo: CONN BASE BOTTOM ENTRY SZ3 Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>110227-HMC510LP5 Abakhiqizi: ADI (Analog Devices, Inc.) Incazelo: BOARD EVAL HMC510LP5E Kukhona kusitoki: 2 pcs</p> <p>RFQ</p>
 <p>1102246-5 Abakhiqizi: Agastat Relays / TE Connectivity Incazelo: CONN BASE BOTTOM ENTRY SZ3 Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>110227-HMC512LP5 Abakhiqizi: ADI (Analog Devices, Inc.) Incazelo: BOARD EVAL HMC512LP5E Kukhona kusitoki: Out stock</p> <p>RFQ</p>
 <p>110227-HMC511LP5 Abakhiqizi: ADI (Analog Devices, Inc.) Incazelo: BOARD EVAL HMC511LP5E Kukhona kusitoki: Out stock</p> <p>RFQ</p>	 <p>110227-HMC514LP5 Abakhiqizi: ADI (Analog Devices, Inc.) Incazelo: BOARD EVAL HMC514LP5E Kukhona kusitoki: Out stock</p> <p>RFQ</p>

I-Copyright © 2020 Distributor Ethembekile Yezingxenywe Ze-elektronikhi - Ocean-Components.com

Imeyili: I-Info@Ocean-Components.com

Ikheli: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

